

Mceathron, Kimberly

From: Kevin Nugent <knugent@gmdshipyard.com>
Sent: Tuesday, September 02, 2014 4:29 PM
To: McEathron, Kimberly
Subject: Status and Progress
Attachments: GMD Shipyard Activity to meet EPA requirements 090214.docx

Good Afternoon, I wanted to send you an update of what we have been doing to respond to your original inspection and the EPA Notice. Attached is a listing and some pictures of activity. I had contacted Mr McKenna within the 20 day time period per the ACO to discuss the time schedule. He reported that you would be the contact. You had noted the pile that was under the tarps during your inspection. We have been trying to get rid of this pile. It had been sampled a few times to be disposed of during this year. Since your visit It has also been sampled again. We have a mover and a means to remove the material. We are waiting for the landfill to accept it. We intent to properly dispose of a this pile. After we have a large section the pile removed, we can then remove the materials from Graving Dock #5 and put it where the removed material had been. Hopefully this is resolved in the next week or so. We do not have another large area to put the material in the dock and we don't want to put it on the already sampled piled material. I will keep you appraised. Attached is some activity directly related to the ACO.

Regards,
Kevin Nugent
HSE Director
GMD Shipyard Corp.

"The email and its attachments may be confidential and are intended solely for the use of the individual to whom it is addressed. Any views or opinions expressed are solely those of the author and do not necessarily represent those of Bayonne Drydock & Repair Corp. If you are not the intended recipient of this email and its attachments, you must take no action based upon them, nor must you copy or show them to anyone".